




09/830,963

Docket No.: 250599US90PCT



COMMISSIONER FOR PATENTS
ALEXANDRIA, VIRGINIA 22313

RE: Inventor: Yogo KAWASAKI, et al.

Patent No.: 6,930,258

Issued: August 16, 2005

Group Art Unit: 2841

Examiner: Ishwar (I.B.) Patel

For: MULTILAYER PRINTED WIRING BOARD AND
METHOD OF PRODUCING MULTILAYER
PRINTED WIRING BOARD

SIR:

Attached hereto for filing are the following papers:

REQUEST FOR CERTIFICATE OF CORRECTION
CERTIFICATE OF CORRECTION FORM PTO 1050

Our check in the amount of \$0.00 is attached covering any required fees. In the event any variance exists between the amount enclosed and the Patent Office charges for filing the above-noted documents, including any fees required under 37 C.F.R 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, please charge or credit the difference to our Deposit Account No. 15-0030. A duplicate copy of this sheet is enclosed.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.

Masayasu Mori
Registration No. 47,301


Roland E. Martin
Registration No. 48,082

Customer Number

22850

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 05/04)

DOCKET NO.: 250599US90PCT/hse



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: Yogo KAWASAKI, et al.

PATENT NO.: 6,930,258

GROUP: 2841

ISSUED: August 16, 2005

EXAMINER: Ishwar (I.B.) Patel

FOR: MULTILAYER PRINTED WIRING BOARD AND METHOD OF PRODUCING
MULTILAYER PRINTED CIRCUIT BOARD

REQUEST FOR CERTIFICATE OF CORRECTION

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE
ALEXANDRIA, VA 22313-1450

SIR:

The following is a request for a Certificate of Correction in Serial Number 09/830,963, now Patent Number 6,930,258.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 254, the Patent Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the Patent Office, no fees are required. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.



Masayasu Mori
Registration No. 47,301

Customer Number

22850

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 05/05)

Roland E. Martin
Registration No. 48,082

SEP 12 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : **6,930,258**
DATED: **Aug. 16, 2005**
INVENTOR(S): **KAWASAKI, et al.**

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item 22, the PCT Filed date is incorrect. Item (22) should read:

--[22] PCT Filed: **Oct. 10, 2000** --

Mailing address of sender:

Patent No. **6,930,258**

Customer Number
22850

No. of add'l copies
@ .30 per page

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 03/02)



SEP 12 2005